PROPERTY RISK REVIEW OUTCOMES

Risk Area / Observations / Recommendations	TDC Response
1. Fire Safety within Residential Properties The insurer highlighted a number of points including:	<i>In respect of the stay put policy - The fire</i> <i>evacuation policy was reviewed reflecting the</i> <i>various properties held within the Council's</i> <i>housing stock. A 'stay-put' policy remains in</i>
 Recognition that work had been undertaken within the Council to verify good fire safety standards are in place. 	place as it is the most reasonable and practical response in the unlikely event of a fire within a block of flats (tallest block within the housing stock is 4 storeys)
 Fire Evacuation (flats) - Currently a 'stay-put' policy is in place, however there are plans to review this, as supported by the insurers, and needs 	The policy will remain under on-going review and will reflect future changes in related guidance.
 to be considered for each property. Communal areas have fire detection and alarm systems so any policy needs to avoid potential confusion and delays in evacuation. Compartmentation - It is understood that the integrity of compartmentation was reviewed by the Council following the Lakanal House fire in London in 2009. It is recommended that 	In respect of compartmentation - Reviews are undertaken during a change of tenants as part of void work and any remedial works carried out. Fire inspections are being carried out on a monthly basis in Sheltered Accommodation. In flats they are carried out on the basis of tenancy turnover and the extent of any damage caused, i.e. in areas of high damage the inspections are carried out on a more frequent basis.
 compartmentation is checked on a regular basis. Integrated Window Systems/Spandrels - A review of these systems should be undertaken to identify any buildings at risk, to ensure that the construction/installation 	In respect of Integrated Window Systems - All windows are compliant with current Building Regulations. Windows in communal areas and stairwells are renewed and upgraded as part of ongoing window replacement works that in turn supports the important compartmentation requirement.
 fixings/insulation type is known, and to verify their integrity and to prevent panels falling prematurely. Guidance to Tenants - Tenants should be provided with guidance on 	Window replacement forms a significant component of the major repair and refurbishment works that are carried out each year within the Council's general housing stock.
which precautions can be taken to reduce the risk of fire spreading between flats, such as open windows, housekeeping, storage on balconies, keeping all fire doors shut etc.	<i>In respect of guidance to tenants -</i> New tenants are issued with a Fire Safety leaflet and periodic updates are sent via the Tenant's newsletter.
 Waste Chutes - If not already in place, there needs to be a mechanism where waste chutes (including hoppers and dampers) are 	<i>In respect of Waste Chutes -</i> Where waste chutes are still in operation any faults would be picked up as part of the routine block inspections which is already in place.

 inspected and maintained on a regular basis. Electrical Maintenance – Consid frequency of electrical tests/inspections within resider flats. Attention was drawn to general guidance relating to rendered insulated buildings, and if applie to the Council, actions to under should include: Check the original construct documentation to confirm i breaks were installed, the positioning etc. Were any inspections undertaken to confirm that these were in sinstalled as proposed? If no construction informati available then sample check (such as core holes drilled) verify the insulation materia used and location of fire breaks of regul building condition surveys f the render, to enable dama render to be repaired prom therefore reinstating a fire protective covering over the insulation Develop a fire fighting strat for this type of building, following discussions with t local fire authority. 	atialevery 10 years, communal areas every 5 years and an annual inspection of emergency light fittings.tableIn respect of rendered insulated buildings - The only insulated render system still in place within the housing stock is the Swisslab system applied to a limited number of properties - Percy King estate, Churchill Court and Grove Avenue.tionThis comprises of a slab insulation mechanically fixed to the structural frame without a cavity and with a polymer render finish with spar chipping dash. Following review of the manufacturer's literature, it is understood that it has good fire resistance and as mentioned above there is no cavity which supports the prevention of a rapid spread of fire.eaks. ar or e to ptlyIt is important to highlight that the tallest block of flats within the housing stock is only 4 storeys and it is not considered necessary to implement alternative policies over and above those that apply to the wider estate as mentioned above e.g. evacuation policy.
rendered/insulated building 2. Northbourne Depot – Gas Cylinders To reduce the risk of gas cylinders toppl and causing injury or damage, all gas cylinders should be kept secured within cages, with separate clearly defined are full/empty cylinders. In addition, Fuel ga (eg LPG) should be stored away from oxidising gases such as oxygen.	ing The relevant service has created a suitable caged area as required, which will be subject to usual checks and reviews as part of the Council's wider risk, health and safety gas processes. as for
3. Unoccupied Properties Some unoccupied properties are subject an annual inspection. As unoccupied properties frequently attract unwanted attention, the inspection frequency sho be increased. We recommend that all	proportionate checks taking into account the level of associated risk.

unoccupied buildings are inspected thoroughly both internally and externally at least weekly and a record maintained of such inspections. Any defects in security and maintenance should be rectified immediately and accumulations of combustible materials should also be removed during these inspections. It was noted that there remains some storage within the Westleigh Property, this should be removed promptly.	All remaining storage has now been removed from Westleigh House prior to its demolition.
 4. Clacton Leisure Centre Kitchen extraction ducts - frequency of the cleaning undertaken and cleaning is completed along its entire length. Sauna – relevant guidance to be reviewed to ensure that the maintenance/management procedures meet the necessary standards to ensure fire safety. 	The kitchen facilities are within a 'commercial unit' that is leased to a third party. The maintenance of the facilities is the responsibility of the lessee. The extraction ducts are checked yearly. The current tenant does not fry food on the premises so not considered to be a high risk. The sauna is currently in use and there is a maintenance agreement in place with an external contractor and it is serviced and maintained monthly. A list of tasks required to be carried out with reference to relevant guidance is undertaken.