HSE Inspection March 2025 – ACTION PLAN

Location	HSE Inspection Primary Comments	HSE Recommendations / Key	Current Status
		Actions	
Town Hall	You have not ensured that the maps provided with your asbestos register and management plan was suitably clear and	Improvements to the Asbestos Management Plans required	Plans updated using new HSE template and shared with HSE.
Princess Theatre	easy to interpret. A number of issues with the maps were identified including;There were no building names marked upon the map,	reference clarity of room numbering, key responsibilities/ duties and named contact	Town Hall, Theatre and Northbourne plans accepted /
Northbourne Deport	making it had to interpret or locate items in the register on site. This issue is exacerbated due to the small size of the map.	officers. 2) Ref the Asbestos Management	closed. HSE requested additional improvements to Clacton Leisure Centre Plan reference room
Clacton Leisure	The numbers on the map are unclear as to what they relate to in relation to the asbestos register.	Plans, ensure room numbers match those on the building	numbering (see below)
Centre	 A number of Asbestos Containing Materials (ACM) identified on the original management survey were not identified on the map. 	layout maps for each site - to be completed by end of June 2025.	 Ongoing for Clacton Leisure Centre. Completion required by 30 June.
	 The room numbers on some maps no longer matches all the room numbers on site. The locations of some ACMs are unclear due to the labelling used on the map. The large red circles used to identify the 	New asbestos survey requested for Clacton Leisure centre to be completed by 30	Started and remains ongoing at the time of finalising this report.
	majority of ACMs are large enough to cover doorways and room names / numbers allowing for the potential for confusion as to the location of ACMs.	June 2025. 4) Fire box to be installed outside	4) Completed.
	Asbestos management plans are not sufficiently detailed for controlling the risks from asbestos management detailing the suitable roles and responsibilities within the business including clearly defined responsibilities relating to annual inspections.	each site. 5) To review Asbestos Management Plans for all sites annually	5) Services reminded of the need for annual reviews and/or as part of any material building works/ changes. Internal H&S team to ensure annual reviews during
	Clear instructions for who is responsible within TDC relating to who provides the relevant information to contractors.		their inspection regime.
	 Reference Clacton Leisure Centre Plan, you must ensure that there are adequate arrangements in place in the event of an accident incident or emergency should there be an unplanned release of asbestos on site. 		